

Specification

Paragraph 0017

[[Pain]] Pane 2 could also include a trace that represents an ideal BMI progression or a band representing the desirable range between which the BMI should progress. [[Pain]] Pane 2 could also include a further band or bands representing a further range existing beyond the desirable range and into which it would be undesirable for the BMI to progress. By the inclusion of these additional traces and bands [[pain]] pane 2 provides a visual indication of condition management targets and the patient's actual progress. Such information could be made accessible by the patient as the clinician determines. Suitable labels can be displayed alongside the data such as "Normal", "Overweight", "Obese", etc. These may be displayed only to the clinician, or to both the patient and the clinician. Additional or alternative labels may be displayed to the patient.